

July 31, 2017

DONAHUE SCHRIBER REALTY LAGUNA CROSSROADS 3501 DEL PASO RD STE 100 SACRAMENTO CA 95835

SUBJECT:

REPAIR / REPLACEMENT OF BACKFLOW PREVENTION ASSEMBLY AT: 7601 LAGUNA BLVD ELK GROVE CA 95758 - DEVICE ID: BD0004599

Dear LAGUNA CROSSROADS:

Background

Sacramento County Code Title 6, Chapter 6.30, Section 6.30.110 requires the Owner and/or Operator to repair or replace any defective backflow prevention assembly (assembly) at their facility. On 7/2/2017, the submitted test report indicated an assembly at this location failed field testing and that repair or replacement of the defective device is required.

Actions Required

You are hereby directed to correct the following violation(s) within fifteen (15) days of the date of this Notice:

- Repair or replace the defective assembly at the water service connection. For a list
 of approved assemblies, visit
 http://www.emd.saccounty.net/EC/Pages/CrossConnection.aspx
- 2. After repair or replacement, the assembly must be tested by an EMD registered backflow assembly tester, and annually thereafter.
- Once the assembly passes field testing, an EMD annually issued tag shall be affixed to the assembly. The tag serial number shall be included on the test report submitted to EMD.
- 4. Completed test reports must be electronically submitted to EMD within 20 calendar days from the date of the test.

Be advised that failure to comply with the above requirements may result in enforcement action being taken against you.

Water Supplier Specifications

Please contact your water supplier for instructions and specifications prior to replacement of any assembly.

REPAIR/REPLACEMENT - BD0004599 - CONTINUED

Questions

If you have questions regarding this Notice, please contact our office at (916) 875-8400 or via email at CrossConnection@Saccounty.net

Sincerely,

Chris Hunley

Environmental Specialist Cross-Connection Control Program

MW:JVB:CWH:KM

c: COUNTY OF SACRAMENTO