COUNTY OF SACRAMENTO ENVIRONMENTAL MANAGEMENT DEPARTMENT ENVIRONMENTAL COMPLIANCE DIVISION 10590 ARMSTRONG AVENUE MATHER CA 95655 (916) 875-0083 • FAX (916) 854-9274 ASSEMBLY INFORMATION

TYPE: RP SIZE: 2.00 MFG: WAT

MODEL: 0092MQT SERIAL NO: 190296

EXISTING » EMD BID REFERENCE # BD0023135

WATER PURVEYOR: COUNTY OF SACRAMENTO

TYPE OF SERVICE: DOMESTIC

## **BACKFLOW ASSEMBLY TEST REPORT**

| FA0044501     |
|---------------|
|               |
| 916) 920-5555 |
|               |
|               |
| OW0024427     |
|               |
|               |

|                 | DOUBLE CHECK VALVE ASSEMBLY |                                   | TEST RESULTS INFORMATION           |                               |                  |
|-----------------|-----------------------------|-----------------------------------|------------------------------------|-------------------------------|------------------|
|                 | REDUCED                     | PRESSURE PRINCIPL                 | E ASSEMBLY PRESSURE VACUUM BREAKER |                               | UUM BREAKER      |
| -               | CHECK VALVE<br>NO. 1        | CHECK VALVE<br>NO. 2              | DIFFERENTIAL<br>RELIEF VALVE       | AIR INLET VALVE               | CHECK VALVE      |
| INITIAL<br>TEST | HELD AT: 9.10<br>PSID       | HELD AT: PSID CLOSED TIGHT (RP) Y | OPENED AT: 2.20 PSID OPENED UNDER  | OPENED AT:  PSID OPENED UNDER | HELD AT:         |
|                 | LEAKED: <u>N</u>            | LEAKED: N                         | 2.0 PSID OR NOT OPEN               | 1.0 PSID OR N<br>DID NOT OPEN | LEAKED: <u>N</u> |

TEST DATE

8/6/2015

COMMENTS: Flushed assembly. Dumped device and exercised RV multiple times and retested resulting in a pass

STATUS: PASSED TAG NO: CP0131

| SACRAMENTO COUNTY TESTER NUMBER | NAME              |
|---------------------------------|-------------------|
| PI0001026                       | RAMIRO CUEVAS JR. |

If the test PASSES, the field testing report(s) shall be filed with EMD within 20 calendar days following completion of the field test.

If the test FAILS, the tester shall report all failed results to EMD and to the water supplier within 24 hours. The tester shall submit all failed testing report(s) to EMD within five (5) calendar days following completion of the field test.

Failure to submit testing results may result in enforcement action.

SUBMITTED TO EMD ON: 8/8/2015 [PROCESS DATE]

